

# PDR RID Report

**Originator** Hughes, Peter **Phone No** 301.286.3120  
**Organization** GSFC Code 522  
**E Mail Address** phughes@kong.gsfc.nasa.gov  
**Document** PDR

<b>RID ID</b>	<b>PDR</b>	9
<b>Review</b>	FOS	
<b>Originator Ref</b>		PH
<b>Priority</b>	2	

**Section** N/A

**Page** N/A

**Figure Table** N/A

**Category Name** Design

**Actionee** HAIS

**Sub Category**

**Subject** STOL Procedure Execution

## **Description of Problem or Suggestion:**

It is unclear whether multiple STOL procedures can be executed simultaneously. Also, can a STOL procedure start another STOL procedure?

## **Originator's Recommendation**

Consider supporting these capabilities.

## **GSFC Response by:**

## **GSFC Response Date**

**HAIS Response by:** D. Herring

**HAIS Schedule** 1/6/95

**HAIS R. E.** J. Creegan

**HAIS Response Date** 1/6/95

Multiple STOL procedures can execute simultaneously (FOS requirement F-FUI-06120). STOL procedures can start other STOL procedures (FOS requirement F-FUI-01575).

**Status** **Closed**

**Date Closed** **2/1/95**

**Sponsor** **Johns**

\*\*\*\*\* **Attachment if any** \*\*\*\*\*